

TID	Tree Location	Remarks	Type	Size	Recommendation		Select Board Vote 6/18/24
					Tree Warden Designee	Arborist	
1	2 Wood St	Oak is dead, covered in vines	Oak	32"	Remove	Remove	N/A
2	10 Meadow	Maple has split cavity	Maple	44"	Remove	Remove	Trim
3	28 Flagg - east side of rd to left of driver feedback sign	Oak dropping wood in road, trim and watch	Oak	48"	Trim	Trim	Trim
4	70 Deerfoot across from pole #41	Oak dropping wood in road, trim and watch	Oak	20"	Trim	Trim	Trim
5	103 Middle #1 near pole #36-84	Dead ash tree hanging over the road	Ash	28"	Remove	Remove	Remove
6	103 Middle #2 right of fire hydrant/across from Stub Toe, across from pole #36	Poor health, leaning over road	Ash	14"	Remove	Remove	Trim
7	Middle @ 54, along reservoir near pole #26	Dead oak double stem over road and wires	Double Oak	40"	Remove	Remove	Remove
8	Middle Rd westside just south of causeway, near pole 25-26	Dead oak	Oak	30"	Remove	Remove	Remove
9	Middle Rd near pole #26	Dead oak with fungus and has a heavy lean	Oak	36"	Remove	Remove	Remove
10	117 Southville southside of mailbox, across from pole 35	Dead oak that is breaking apart	Oak	30"	Remove	Remove	Remove
11	Across from 121 Southville to left of mailbox, across from pole #33/34	Dead oak that is breaking apart	Oak	12"	Remove	Remove	Remove
12	Across from 123 Southville, across from pole #32/33	Dead ash tree that are breaking apart	Ash	20"	Remove	Remove	Remove
13	Across from 123 Southville, across from pole #32/33	Dead ash tree that are breaking apart	Ash	28"	Remove	Remove	Remove
14	Across from 123 Southville, across from pole #32/33	Dead ash tree that are breaking apart	Ash	20"	Remove	Remove	Remove
15	Southville across from handtub bldge across from pole #31	Dead ash that is breaking apart	Ash	20"	Remove	Remove	Remove
16	127 Southville westside corner of house	Dead oak that resident is concerned about	Oak	20"	Remove	Remove	N/A
17	16 Walnut Dr	Dead oak with no foliage and dropping limbs	Oak	48"	Remove	Remove	Remove
18	202 Parkerville #1	Tree is dying and loosing limbs	Ash	24"	Remove	Remove	Remove
19	202 Parkerville #2	Tree is dying and loosing limbs	Ash	30"	Remove	Remove	Remove
20	60 Richards Rd close to main exit for school, along sidewalk	Dead tree, no foliage, dropping limbs over sidewalk, school and road	Ash	24"	Remove	Remove	N/A
21	Near 140 Woodland, over wires	Tree sitting on wires (primary) has significant burning. Nat'l Grid has concerns about safety ove wires and road	Oak	20"	Trim burned limb	N/A-Poss Trim	Trim
22	16 Deerfoot Tree #1	Tree dying and dropping limbs	Maple	24"	Remove	Remove	Remove
23	16 Deerfoot Tree #2	Partially dead tree and is dropping limbs	Maple	24"	Remove	Remove	Remove
24	16 Deerfoot Tree #3	Partially dead tree and is dropping limbs	Maple Elm	36"	Remove	Remove	Trim
25	Across from 2 Stowe Rd	Damaged roots, smothered w/vine and leaning	Oak	36"	Remove	Remove	Remove
26	61 Edgewood	Cavity rot	Oak	28"	Remove	Remove	Remove